Additional Research on Fred & Elsa Schmidt House 2613 Capitol Way S

- This building is a Contributing property in the National Register of Historic Places-listed South Capitol Neighborhood Historic District. The nomination form for this designation indicates that the building was constructed in 1912 and that Orrin Green, President of Olympia National Bank, was a resident here in 1932.
- The Thurston County Assessor also lists the construction date for the property as 1912.
- Sanborn Fire Insurance Company maps show the property before the front yard was subdivided and developed. The 1951 Sanborn map update does not show the footprint of the building as it appears now. However, other Thurston County Assessor photos indicate that it was significantly renovated at some point between 1939 and 1946.
- Thurston County Assessor records indicate that the duplex that occupies the former front yard of the house (2611 & 2615 Capitol Way S) was built in 1952.
- *Polk's City Directories* provide some information on Karl L. Strandberg (and family), the person who reportedly remodeled the house in the 1940s.

Current Map of Area



Figure 1: Area Map, Olympia Online Mapping, Accessed November 21, 2016

Polk's Directories on Karl L. Strandberg and Family

1930-31	= First mention of Strandberg family name → Otto (millworker Washington Veneer Co.)
1939	= First mention of Karl L. (building contractor) & Opal N. @ 122 N Turner
1941	= Karl L. (building contractor) & Opal N. @ 527 14 th Ave E
1943	 Karl L. (building contractor) & Opal N. @ 527 14th Ave E Alice O. (clerk SDofL) @ 527 14th Ave E
1946	 Strandberg Construction Co. @ 206 Thurston Ave E Karl L. & Opal N. @ 2613 Capitol Way Alice O. @ 2613 Capitol Way
1947-48	= Karl L. & Opal N. (general contractor) @ 206 Thurston Ave E; h. @ 2613 Capitol Way= Alice O. @ 2613 Capitol Way
1949	 Karl L. & Opal N. @ 530 Vista Av** (NB: No longer as contractor in yellow pages) Stanley L. (student) @ 530 Vista Av**
1951-52	= Karl L. & Opal N. @ 530 Vista Av** = Stanley L. (student) @ 530 Vista Av** = Hugo (carpenter) @ 208 13 th Ave E
1954	= Karl L. & Opal N. @ 530 Vista Av** = Hugo (carpenter) @ 208 13 th Ave E
1955	 Last mention of Karl L. (builder) h. @ 621 Capitol Way Hugo (millworker, Hardel Plywood) @ 208 13th Ave E
1957	 Opal Mrs. (employee Caton's) h. @ 313 E 27th Av Hugo (millworker, Hardel Plywood) @ 208 13th Ave E
1958	 Last mention of Opal Mrs. (employee Caton's) h. @ 313 E 27th Av Hugo (millworker, Hardel Plywood) @ 208 13th Ave E
1960	Stanley L. (draftsman, Robt H. Wohleb & Assocs.) h. @ RD8 Box 480)Hugo & Elna (Sav-Mor Food Center @ 1055 Capitol Way
1961	No mention of Karl, Opal, Alice or StanleyHugo & Elna (Sav-Mor Food Center @ 1055 Capitol Way

^{**530} Vista Ave SE, Tumwater, WA – Thurston County Assessor indicates 1948 as year built. No other former residences listed appear to be in existence today. Google image of 530 Vista Ave SE:





Figure 2: Thurston County Assessor Photo, ca. 1939. Courtesy of the Washington State Archives.



Figure 3: Thurston County Assessor Photo, ca. 1946. Courtesy of the Washington State Archives.

	Lui grad	Remas	Cem. Sel.	Brick Vest.			Aluminum	Galy, Iree	Stone	TIM	Stude Mar'y	Stuess	Shakes	Shingles	Cadar	Shipius	Rustio	Brd. & Bats	EXT. WALLS		Piles	Parts	Stone, Briek	Cosoreta	FOUNDATION			Paultry	Barn	Bas Stat.	Green beuse	Warning	Papery	Lt. Mfg.	Com 'l Bar.	Hall	Bank	Theatra	Store	Hotel	Model	Court ApL	Apartment	Duplex	Dwelling	Carlo
	CHAND IN	LIGHTIMB			Auto. Sprin.	Elevator	Plata Glass	Ventil. Byt.	Bearn Cell.	Book Cases	Bay Window	Dormers	EXTRAS		Air Cond.	Casi Staker	Gas Burner	OH Burner	Panel Rad.	Base B. Rad.	Floor Rad.	Cencelled	C. I. Rad.	Pipe Furn. (A	Pipeless Furn.	Floor-Will	Stores	HEATING	-	Insulation()	MIII May	THE PLOTON	Conorete	Briek	Frant	Double	Single	COMSTRUCT.		Tar & Gravel	Shakee	Shingles		/ Gable	H.	ROUT
Q No. Fixture		Automatio Washer		H. W. Heater	Dish Washer	Garbage Disp.	Sink V	Sheer.	TH G.	PLUMBING	- Commander	Dirt Fleor	Concrete Floor	7 Part	Full	BASEMENT		Carpet & 7	Lineleum	Asp. Tile	Cangrate	Hard	Sett	7	Mertal	Marble	HII	Hardweod	1	TRIM	1	Platter Div.	Plant no.	Wall Bears	CEILED .		Neek	Utility	SE	Bath	Bed		Kitoless /	Living	Halle	14
							-	4 81	274	DMI						ENT							17					-			1	1								W.	1					>
		THE ROW HOUSE THE WASH	COMOS HOME ENTERED	The state of the s	0,5	mai Rod Paintings	REMARKS (LECTION OF CLUB TO LAND TO STATE OF THE PARTY OF	Rate Variation	Tetal					HEAT	MI (AMM)	NAP.	(Pappar)	Hats Adj.		+					+:			8				+ + + + + + + + + + + + + + + + + + + +			+ + + + + + + + + + + + + + + + + + + +			+ • • • • • • • • • • • • • • • • • • •		++	Used For RES	A. 100 100	W V1	Teal He-Med.	1	Your Built 1717
		8710. 87.18681	100	A length /	1	O danations.		-	10,	1	8		No.	.//	Y	-	1	+	+	+		, h.G.					+ + + + + + + + + + + + + + + + + + + +		2.2			++			+ + + + + + + + + + + + + + + + + + + +			+			Listed by-	California (California California	Candillins	Cent		Class
		7	X . 787 -4 425 muit.	201		Par Management	Cally all Hand			Transfer of the second	To Compense	Height	Perization 2 4		a a	ta.	X		10.24	+					+::::::::::::::::::::::::::::::::::::::	**	+	: :t		+ : 5		+			+			+			- GH K 2.	11111	FAIR	-		HIER -
			WULL.			0	mula	-				7	56	28/ 00		1	**************************************	00		34.56. 25					+		+ +			† :		+			+			+ -		- +	2-19-53		2 4	1		1108
145 5-6 1070	1 1 10 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	7. 21 19 57	Appraised by					Total Assessed Value % 2)	Total Present Value	Additional Bulldings	Present Value	ACT TO STATE SOURCESTONO	1	14 think from 1 114		Base Cost 2656 50 23.94	Adjustments	1000	W IVLOIL				SOLVANIA 386 NOHIO 1.20	The state of the s		6	Plumaing S. E. Than 334 448	Hantlag 2 45-65F	Comment Process	SE ET	0 6		ADDED FEATURES	TWIGE						CATBIOL FIKEPIAN	L	1012 1000	DS 88 C	-16-14 1585 That	Burngel x See	ADDIAMAL BUILDIAMS
	ANDRA TEL	RUB		-				79,500	72.570	300	12/4/0	18/100	10000	200 9/06	79 180	63,575		000) 101	_			1	1000			2500	1335	5	530	1	e e	2		300	-					100		_	N Y	# 200		Filet
	SAMORA TRIMBLE /- 1619 8	1.27	4				,	23/00	22/000	700	9	a cons	-	1,01	28/773	2,000 38855			740		-	1	+	1		***	795	J	-	30/000		2/91		1/00						-			1986			Second
19	18 61	19 77		1000				53.350	23.342	000	Lady &	7000	109/6	29663 564	4744	38855		0/04				-	0	2 de	-	320	990		315	100	3	-	-	850	1	1	_		-	1	100	4.4	/	400		third

Figure 4: Thurston County Assessor Field Notebook. Courtesy of the Washington State Archives.



Figure 5: House location on 1924 Sanborn map. Digital image care of Timberland Regional Library.




Figure 6: House as illustrated on the 1951 updated Sanborn map (see Fig. 7)




Figure 7: Index page for 1951 update to 1924 Sanborn Fire Insurance Map (see Fig. 6).

Current Photos



Figure 8: Front (West) Elevation from Driveway - Facing North-Northeast (September 14, 2016)



Figure 9: Side (North) Elevation – Facing Southeast (September 14, 2016)



Figure 10: Side (North) Elevation – Facing Southwest (September 14, 2016)



Figure 11: Rear (East) Elevation (September 14, 2016)



Figure 12: Side (South) Elevation from Driveway (September 14, 2016)




Figure 13: Kitchen Detail Showing Window Light Design (September 14, 2016)



Figure 14: South-Facing Windows (September 14, 2016)



Figure 15: North Addition Juncture (September 14, 2016)



Figure 16: Floor Joist Detail (Provided by the applicant, September 15, 2016)



Figure 17: Floor Joist Detail (Provided by applicant, September 15, 2016)