## PROJECT DESCRIPTION

Project includes roof repair of entire building over Suites 113-117.

The building Owner is requesting exemption from full compliance with the 2015 WSEC as allowed by Par. C503.3.1: The existing building has no insulation above the roof deck. The project will improve the energy efficiency of the building as it incorporates the four inches of polyisocyanurate rigid insulation above the roof deck.

The project incorporates skylights with a total area equal to 96sf, below 3% as identified in C402.4.1 (3360x3% = 100.8sf)