



Ivina Room

PORCH







Specifications-Style 361 & 126

- FOUNDATION:--Raised 2 feet from ground. Sufficient beams and posts 6x8, thus eliminating brick partition in basement. FRAME:--2x8 first floor joist and box sills; 1x3 bridging; 2x4 studding: 2x6 rafters and 2x8 ceiling joists. Partition studding in attic. FLOORS:--Subfloor 1x10: 13/16x34," vertical grain flooring; attic floor of shiplap.
- WALL:--S'-6" ceiling, double constructed throughout: 1x8 shiplap; felt paper; 6" cedar siding.
- Paper; 6° cedar siding.  $ROF:=Mo.1 = A^*$  cedar shingles on 1x6 surfaced sheathing; 2' pro-jection lined with 1x4 V ceiling; porch columns. **INTERIOR FINISH:**—S" base board and shoe; 5" Mission casing and special head casing; picture mouldings for all rooms.

**BUILT-IN FEATURES:**—No. 361—Buffet; kitchen cabinets; cooler; breakfast table and seats; linen closet; book cases at each side of fire place; sheiving for closets; medicine cabinet; French doors. No. 126—Kitchen cabinet with cooler; breakfast nook; linen closet; medicine cabinet; seat in bay window and each side of fire place; shelving.

- Day window and each side of the place; subving, PAINT:—Exterior—two coats of paint or stain. Interior—three coats of white or ivory paint, or filler, varnish and stain. LATH:—No. 1 sath for all inside plaster work. MATERIAL:—All lumber and millwork furnished in No. 1 clear and common Douglas fir.

HARDWARE:--All rough and finish hardware. Finish hardware in old copper or brass plated cylinder front door lock; flashing; down spout.

For Price List See Last Page

Page Thirty-One



Catalogue of Tumwater Lumber Mills and publicity still of the house at 208 18<sup>th</sup> Ave SW



Current condition of the house at 208 18<sup>th</sup> Ave SW