

Attachment 1  
Rehabilitation Photos – Trena & Leo Belsito House (408 27<sup>th</sup> Ave SE)


During Construction



Sewer upgrades and rehabilitation work on the front porch and balcony.



Complete reroof, gutter, and chimney rehabilitation.



Framing the upgraded kitchen.



New master bathroom in the works.

After Project Completion



Front Elevation




Front Entrance



Rear Elevation



Front Entrance Hall – Original railings and radiators



Downstairs Bathroom – Original fittings



Family Room – Windows and floors refurbished



New Kitchen Buildout – Previous kitchen fixtures not original



Dining Room and Ballroom Doors – Refurbished character-defining features



Ballroom – Fixtures and fittings restored to a high standard